



CEDRONI ASSOCIATES INC.

General Contractors

5639 Auburn Rd.

Utica, MI 48317

Phone (586) 254-7778

Fax (586) 254-4517

TITLE: Glass Block Windows

REQUEST FOR INFORMATION

NO. 5

PROJECT: Ford Field Comfort Station

DATE: 04/09/2018

TO: Attn: Eric Stockwell
NSA Architects
23761 Research Drive
Farmington Hills, Michigan 48335

RECEIVED

4/9/2018

STARTED:

COMPLETED:

REQUIRED:

NSA

REQUEST:

- (A) Regarding possible relocation of glass block windows. As discussed at the meeting, the windows did not fall on bond, possibly causing structural concerns for the support of the bond beams above the windows. Shifting the windows to an "on bond" alignment is ideal.
- (B) Also, are the two courses of bond beam underneath the windows required? Please advise.

ANSWER:

(A) GLASS BLOCK WINDOW LOCATIONS CAN SHIFT EAST (TOWARD ACCESSIBLE STALL) TO BE ON BOND.

(B) THE TWO BOND BEAM COURSES UNDERNEATH THE WINDOWS WILL NOT BE REQUIRED.

Requested By: Cedroni Associates, Inc.

Date: 04/09/2018

Signed:

Brian M. Lundberg